


Performance Graph For LO980CP



Values do not include the presence of general manufacturing tolerances or other restrictions in the system supply pipes which may cause differing values on installation. The flow rates are taken with the control handle in mid position.

Intatec Ltd have taken all reasonable care to ensure that the information published is accurate at the time of publishing, however as we continually strive to improve the quality of our products, they may be subject to change. Because of this we recommend confirmation of any critical information with our dedicated team of technical staff who will be only too happy to help.

